

# NEVADA DIVISION OF WATER RESOURCES DRILLING INSPECTION REPORT

1. Date: 06-19-17
2. Location: Legal T02S R40E SEC.29 SWSW  
Street Address \_\_\_\_\_  
APN \_\_\_\_\_  
County ESMERALDA
3. Drilling Company: Boart Longyear
4. ~~Licensed~~ Driller on Site: Name Tom Trujillo  
License Number \_\_\_\_\_  
Rig Type BK-7
5. Intent Card Filed: # \_\_\_\_\_ Date Filed \_\_\_\_\_
6. Type of Operation: New Well ☒ Deepening \_\_\_\_\_  
Reconditioning \_\_\_\_\_ Abandonment \_\_\_\_\_
7. Type of Well: Monitor \_\_\_\_\_ Test \_\_\_\_\_ Dewater \_\_\_\_\_ Waiver # \_\_\_\_\_  
Municipal \_\_\_\_\_ Commercial \_\_\_\_\_ Irrigation \_\_\_\_\_ Permit # \_\_\_\_\_  
Domestic \_\_\_\_\_ Replacement Well \_\_\_\_\_
8. Casing: Steel \_\_\_\_\_ PVC ☒  
Outer Diameter 4" Wall Thickness Sch 80
9. Seals: Sealing Depth Measured \_\_\_\_\_ Sealing Material on Site \_\_\_\_\_  
Cement \_\_\_\_\_ Bentonite \_\_\_\_\_ Number of Bags \_\_\_\_\_
10. Plugging: Casing Perforated or Pulled \_\_\_\_\_ Where \_\_\_\_\_  
Plugging Material \_\_\_\_\_  
Material Volume \_\_\_\_\_  
Static Water Level \_\_\_\_\_
11. Note Problems, Violations or Particulars Below:  
Installing instrumentation borehole Piezometer.  
Intends total depth to be 3000 feet.  
Current depth 467 feet.  
Drilling Under NAC. 534.4376.

Inspector


Michael Scott  
Michael Scott



GPSmap 60CSx

Location  
 $\pm 14'$

N 37.72927°  
W 117.57000°



GARMIN

FIND

MARK

PAGE

MENU














 **BOART  
LONGYEAR**



